

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

ER721
North
> 1
1.016 mi.
5367 ft.

CONCHEIRO,KATHERINE
2165 WEST 7TH ST
BROOKLYN, NY

NY Spills S107416493
N/A

Site 1 of 2 in cluster ER

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name: CONCHEIRO,KATHERINE
Address: 2165 WEST 7TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0509114 / 2006-04-24
Facility ID: 0509114
Facility Type: ER
DER Facility ID: 304848
Site ID: 354836
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2005-10-15
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2005-10-29
CID: 38
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-10-29
Spill Record Last Update: 2006-04-24
Spiller Name: CONCHEIRO,KATHERINE
Spiller Company: CONCHEIRO,KATHERINE
Spiller Address: 2165 WEST 7TH ST
Spiller Company: 001
Contact Name: CONCHEIRO,KATHERINE
DEC Memo: "Nov. 7, 2005 A Basement Suction Line Failure letter was sent to the homeowner of this address. There appears to have been a leak from the oil suction line under the cement floor. An investigation (borings) is required to determine how large the spill under the floor is. The letter suggests the homeowner should call their homeowner's insurance company. 11/21/05 -Sharif//I inspected the basement on 11.17.05. Part of the gravity fed oil line(AST) runs underground, that had been leaking. For how long and what amount of oil had been soaked up onto the ground are undetermined.I suggested Ms.Katherine that the old oil line needs to be dug out for proper determination of oil lost and contamination. If it seems like a minor contamination, end point samples after the excavation should reveal the level of contamination.If it is a major oil leak, soil borings should be installed to determine the subsurface impact.Currently, she is working with the bid with couple of Remedial contractors. 03/31/06 Sharif Rahman- CSL was resent to John Concheiro 2165 W 7TH St Brooklyn, NY 11223-3716 04/24/06 Sharif Rahman- Rec'd invoice from PTC.Home owner Ms. Katherine Concheiro was comfortable with the clean up job.NFA required."
Remarks: "BAD OIL LINE. SMALL STAIN THAT GOES INTO CONCRETE. OIL LINE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REPLACED. APPROX 2 CUPS OF OIL."

All Materials:

Site ID:	354836
Operable Unit ID:	1112226
Operable Unit:	01
Material ID:	2102269
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported